HISTORIC AMERICAN BUILDINGS SURVEY INDEX TO PHOTOGRAPHS



Addendum to:

Paschall House NW corner Spruce and Mattis Streets Philadelphia Philadelphia County Pennsylvania (drawings first transmitted) HABS No. PA-128-B

Jack E. Boucher, photographer. Dates of photos are noted in captions.

BEFORE 1963-65 RESTORATION

PA-128 B-1 SOUTH (FRONT) ELEVATION, WITH CANOPY. Taken November, 1958

PA-128 B-2 WEST ELEVATION. NOTE ABSENCE OF CANOPY. Taken February 21, 1961

PA-128 B-3 BRICKED OVER WINDOW ON SECOND FLOOR ABOVE STAIR IN REAR ROOM. Taken November, 1958